





## SENSOR OPERATION

### TOGGLE CTS-41T (push ON / push OFF)

- The sensor is in the open status after power supply connection (LED is off).
- The first contact will put the sensor in the closed status (LED is on).
- The second contact will put the sensor in the open status again (LED is off).

### SINGLE KEY CTS-41S (hand approaches, the sensor turns ON. Hand moves away, the sensor turns OFF)

- The sensor is in the open status after power supply connection (LED is off).
- When you move the hand closer, sensor switches ON (LED is on).
- When you move the hand away, sensor switches OFF (LED is off).

## STATUS SIGNALLING

indicator	operation
orange LED	<b>continuous light</b> – sensor is closed <b>no light</b> – sensor is open

## ORDER CODE

PRODUCT	
CTS-41	
PERFORMANCE	
T	TOGGLE (push ON / push OFF)
S	SINGLE KEY (Hand approaches, the sensor turns ON. Hand moves away, the sensor turns OFF.)
TERMINAL BLOCK TYPE	
0	angled
1	straight
CTS-41 T - 0	AVAILABLE PRODUCT ALTERNATIVES

## ACCESSORIES

### Standard – included in price of the sensor

- 1x both-sided adhesive layer

### Optional – at extra charge (see catalogue sheet)

- 2x screws with countersunk head 3.5x16 mm

verze 11/2021

Sensormatic srl Via della Beverara 13 - 40131 Bologna  
Tel. 051 6353 511



QMS  
ISO 9001

**Dinel, s.r.o.**  
U Tescomy 249  
760 01 Zlín, Czech Republic

Phone: +420 577 002 003

sale@dinel.cz  
www.dinel.cz